

IC-2720H

Cross Band Repeat

To activate the cross band repeat function:

Push and hold *LOW* and *DUP*, then press and hold *SET* for 2 seconds

To cancel the cross band repeat function:

Push and hold SET for 2 seconds.